

# Table of Contents

<b>ABSTRACT</b> .....	I
<b>ABSTRACT (in Chinese)</b> .....	II
<b>1. INTRODUCTION</b> .....	1
<b>2. PROPERTIES OF THE BICTMD</b> .....	2
2.1 Properties of the BiCTMD in the Modal Space .....	2
2.2 Properties of the BiCTMD in the Building Space .....	4
<b>3. VALIDATION OF THE EFFECTIVENESS OF THE BICTMD</b> .....	8
3.1 The Example Building and Selected Ground Motion Records .....	9
3.2 Elastic Seismic Responses of the Example Building .....	10
3.3 Inelastic Seismic Responses of the Example Building.....	16
<b>4. SUMMARY AND CONCLUSIONS</b> .....	17
<b>Appendix I</b> .....	19
<b>Appendix II</b> .....	20
<b>REFERENCES</b> .....	33

## List of Tables

<b>Table 1</b> The modal properties of the example building and those of the corresponding uncoupled building .....	10
<b>Table 2</b> The 3DOF modal properties of the example building, in which the mode shape $\phi_n$ is normalized to have $\phi_{xn,j} = 1$ .....	10
<b>Table 3</b> The properties of the BiCTMD (units: ton, kN, m, rad, sec) .....	12
<b>Table 4</b> The mean reduction ratios of the 20 peak floor edge translations .....	12
<b>Table A1</b> (a) The stiffness matrices of the 8-storey example buildings (units: kN, m, rad) .....	21
<b>Table A2</b> (a) The properties of the CTMDs used for the 8-storey example buildings (units: ton, kN, m, rad, sec) .....	24
<b>Table A3</b> The percent reductions of edge peak translation of the 8-storey example buildings. (a) the 1995 Kobe earthquake .....	27

## List of Figures

<b>Figure 1</b> (a) The 3DOF model, (b) the typical floor plan and (c) the elevation of the 20-storey example building.....	8
<b>Figure 2</b> The roof translational and rotational frequency response functions, (a) $H_x$ , (b) $H_z$ and (c) $H_\theta$ , of the example building with and without BiCTMD.....	13
<b>Figure 3</b> The analytical model of the BiCTMD .....	13
<b>Figure 4</b> The roof (a) X-translaional, (b) Z-translational and (c) rotational response histories at the CM of the example building subjected to the 1940 El Centro earthquake.....	14
<b>Figure 5</b> The roof (a) X-translational, (b) Z-translational and (c) rotational response histories at the CM of the example building subjected to the 1989 Loma Prieta earthquake ...	15
<b>Figure 6</b> The peak edge translations of each floor of the example building with and without BiCTMD, for the (a) X- and (b) Z-directions under the 1940 El Centro earthquake, and the (c) X- and (d) Z-directions under the 1989 Loma Prieta earthquake.....	16
<b>Figure 7</b> The mean energy demands of the example building (a) with and (b) without BiCTMD under the 1940 El Centro earthquake. The mean energy demands of the example building (c) with and (d) without BiCTMD under the 1989 Loma Prieta earthquake .....	17
<b>Figure A1</b> The roof translational and rotational frequency response functions, $H_z$ and $H_\theta$ respectively, of (a)-(b) Building TS, (c)-(d) Building TSS, (e)-(f) Building TF with the 1 <sup>st</sup> -mode controlled dampers and (g)-(h) Building TF with the 2 <sup>nd</sup> -mode controlled dampers. ....	25
<b>Figure A2</b> The selected ground motion records of (a) the 1995 Kobe earthquake recorded at the JMA station, and (b) the 1989 Loma Prieta earthquake recorded at the LGPC station.....	28
<b>Figure A3</b> The roof translational response histories of Buildings (a) TS, (b) TSS, (c) TF with the 1 <sup>st</sup> mode controlled dampers and (d) TF with the 2 <sup>nd</sup> mode controlled dampers subjected to the 1995 Kobe earthquake. ....	29
<b>Figure A4</b> The roof rotational response histories of Buildings (a) TS, (b) TSS, (c) TF with the 1 <sup>st</sup> mode controlled dampers and (d) TF with the 2 <sup>nd</sup> mode controlled dampers subjected to the 1995 Kobe earthquake. ....	30
<b>Figure A5</b> The roof translational response histories of Buildings (a) TS, (b) TSS, (c) TF with the 1 <sup>st</sup> mode controlled dampers and (d) TF with the 2 <sup>nd</sup> mode controlled dampers subjected to the 1989 Loma Prieta earthquake.....	31
<b>Figure A6</b> The roof rotational response histories of Buildings (a) TS, (b) TSS, (c) TF with the 1 <sup>st</sup> mode controlled dampers and (d) TF with the 2 <sup>nd</sup> mode controlled dampers subjected to the 1989 Loma Prieta earthquake.....	32